



EVAL INSPECTION — ADVANCED — MOTOR GRADERS

2013 Caterpillar 14M
stock: 0UJ00983
serial: CAT0014MKR9J00983
Kabine med AC • Høj kabine • EH Controls • 4.88 m (16 ft.)
Blade • Træk på alle hjul • Dozer Blade • Snevinge
Garanti ukendt

STORAGE LOCATION
Brandt Tractor Ltd. / 765332
Val-D'Or, QC, J9P 0J6
Contact:

PHOTOS (0 Total)

SUMMARY

Overall Condition:
Overall Comments: -RUBBER DE PORTE DECOLLER -REPARER, OK -PORTE CABINE DROITE, VITRE CRAQUER
Evaluator's Name: 63017
Operated Machine: No
Hours: 15,511

							Estimated Cost			
	E X C	G O O D	A V G	F A I R	P O O R	N / A	Comments	Parts	Labor	Total
General Appearance		X						0	0	0
Instruments / Controls		X						0	0	0
Cooling System Checks				X				0	0	0
Engine Checks			X				FILTRE A FUEL A CHANGER ET SEPARATEUR D'EAU	0	0	0
Transmission Checks		X						0	0	0
Differential, Brakes and Final Drive Checks		X						0	0	0
Hydraulic System Checks		X						0	0	0
Chassis and Frame Checks		X						0	0	0
Ground Engaging Tools		X						0	0	0
Tires / Rims		X						0	0	0

GENERAL APPEARANCE

								Comments	Estimated Cost		
									Parts	Labor	Total
Sheet Metal		X									
Rust / Corrosion			X								
Paint			X								
Seat / Seat Belt / Rotation						X					
Doors / Glass		X									
Lights		X									
Mirrors		X									
Cab Interior		X									
Periodic Maintenance						X					
PIPS Complete						X					
Parking Brake / Linkage / Lock		X									
Decals			X								
Operators Manual						X					
Pilot Shut Off / Neutral Lock						X					
Shields/Guards(Drive Shaft)		X									
Section Summary		X									

INSTRUMENTS / CONTROLS

								Comments	Estimated Cost		
									Parts	Labor	Total
Hour Meter: Original ☒ Yes ☐ No Operating ☒ Yes ☐ No		X									
Charging System		X									
Engine Oil Pressure Gauge		X									
Temp Gauges(Eng,Trans,Hyd)		X									
Switches (Key, MFWD, Propel, etc.)		X									
Neutral Start Circuit		X									
Alarms (Travel, Backup)		X									
Monitor / Indicator Circuits		X									
Air Restriction Indicator		X									
Section Summary		X									

Stock Number: 0UJ00983

Model: 14M Serial Number: CAT0014MKR9J00983

COOLING SYSTEM CHECKS

							Estimated Cost			
	NEW	GOOD	USABLE	REPAIR	REPLACE	N / A	Comments	Parts	Labor	Total
Coolant Level / Quality					X		MANQUE BEAUCOUP			
Coolant Operating Temperature		X								
Coolant Leaks					X		DES GOUTTES VIENNENT DU MOTEUR, COULE AU SOL			
Head Gasket Leakage				X						
Water Pump Check			X							
Fan Blades / Pulleys / Shrouds		X								
Fan Guard		X								
Belts / Hoses / Clamps		X								
Radiator / Oil Cooler Condition		X								
Radiator Mounts		X								
Air Conditioning System Check		X								
Section Summary				X						

ENGINE

Make	Size	Serial Number	Tier Rating	Type
CAT ACERT		TXE07908		

ENGINE CHECKS

							Estimated Cost			
	NEW	GOOD	USABLE	REPAIR	REPLACE	N / A	Comments	Parts	Labor	Total
Oil Level / Quality		X								
Oil Scanned? ☐ Yes ☒ No		X								
Air Intake System Check		X								
Engine Start-Up		X								
Engine RPM (Low Idle)		X								
Engine RPM (High Idle)		X								
Fuel Leaks		X								
Inj Pmp / Supply Pmp / Fuel Filter		X								
Oil Leaks		X								
Exhaust System		X								
Does Engine Miss		X								
Excs Smoke (Fuel / Oil / Coolant)		X								
Adequate Power		X								
Adequate Oil Pressure		X								
Speed Control Check / Linkage / AI		X								
Abnormal Engine Noise		X								
TurboCharger Check		X								
BlowBy Check		X								
Compression Check (if Required)						X				
Loose / Worn Parts		X								
Section Summary			X				FILTRE A FUEL A CHANGER ET SEPARATEUR D'EAU			

TRANSMISSION CHECKS

								Estimated Cost		
	NEW	GOOD	USABLE	REPAIR	REPLACE	N / A	Comments	Parts	Labor	Total
Oil Level / Quality		X								
Oil Scanned? ☐ Yes ☒ No		X								
Oil Leaks		X								
Flywheel Clutch / Dampners		X								
Torque Converter Stall / Lock Up		X								
Splitter Box		X								
Trans Oil Pres (Ctrl/Engagement)		X								
Gear Mesh (Manual Transmission)		X								
FNR Operation		X								
Rate of Shift Modulation		X								
Shifting Linkage Adjustments		X								
Clutch / Brake Slippage (Pwr Shft)		X								
High / Low Shifting Performance		X								
Engine Pull Down		X								
Abnormal Transmission Noise		X								
Section Summary		X								

DIFFERENTIAL, BRAKES AND FINAL DRIVE CHECKS

								Estimated Cost		
	NEW	GOOD	USABLE	REPAIR	REPLACE	N / A	Comments	Parts	Labor	Total
Oil Level / Quality		X								
Oil Scanned? ☐ Yes ☒ No		X								
Oil Leaks		X								
Drive Lines / U-Joints		X								
Axle Oscillation Joints		X								
Mounting Hardware		X								
Differential Gear Noise		X								
Diff Lock / Limited Slip Check						X				
Service Brake Operation / Leakage		X								
Steering Clutch / Brake Operation		X								
Front Wheel Drive Operation		X								
Section Summary		X								

HYDRAULIC SYSTEM CHECKS

								Estimated Cost		
	NEW	GOOD	USABLE	REPAIR	REPLACE	N / A	Comments	Parts	Labor	Total
Oil Level / Quality		X								
Oil Scanned? ☐ Yes ☒ No		X								
Oil Leaks		X								
Oil Operating Temperature		X								
Hydraulic Pump Perf / Cycle Times						X				
Abnormal Pump Noise		X								
Sys Chk / Related Cyl / Pvt Jnts		X								
Hoses / Lines		X								
Axle Suspension / Accumulator		X								
Aux Hyd / Valve						X				
Control Valves / Relief Valves		X								
Steering Operational Check		X								
Steering Priority Vlv Opr Check		X								
Section Summary		X								

CHASSIS AND FRAME CHECKS

								Estimated Cost		
	NEW	GOOD	USABLE	REPAIR	REPLACE	N / A	Comments	Parts	Labor	Total
Main Frame		X								
Equipment / Engine Frame		X								
Axles / Tie Rods		X								
Circle Frame		X								
Cab / ROPS Frame		X								
Frame Articulation Joints		X								
Section Summary		X								

GROUND ENGAGING TOOLS

									Estimated Cost		
	% remaining	NEW	GOOD	USABLE	REPAIR	REPLACE	N / A	Comments	Parts	Labor	Total
Blades			X								
Cutting Edge			X								
End Bits			X								
Ripper			X								
Teeth / Tips			X								
Section Summary			X								

TIRES / RIMS

											Estimated Cost		
	Tire size	Tire ply	% remaining	NEW	GOOD	USABLE	REPAIR	REPLACE	N/A	Comments	Parts	Labor	Total
Front: Right	20,5R25				X								
Front: Left	20,5R25				X								
Drive: Right	20,5R25				X								
Drive: Left	20,5R25				X								
Trailer: Right	20,5R25				X								
Trailer: Left	20,5R25				X								
Section Summary					X								