Model: 60D



EVAL INSPECTION — QUICK — COMPACT EXCAVATORS

2009 John Deere 60D Stock: 378383 Serial: FF060DX280238 Cab w/ AC • Short Arm • Rubber Track Warranty Unknown STORAGE LOCATION United Construction & Forestry, LLC / 176339 Clifton Park, NY, 12065 Contact: Joseph Russo TM/CP for Town of Greenport, Ny John Mausolf

PHOTOS (29 Total)









SUMMARY

Overall Condition: FAIR
Overall Comments: Mach

Overall Comments: Machines overall appearance is fair as the cab is pretty beat up including a sizeable dent on entry side. The undercarriage is original and will need changing eventually with exception of front drives one both side, they're fairly new. The machines boom is tight relatively speaking. I feel due to overall appearance this machine might be a hard sale. Evaluator's Name: Joseph Russo

Evaluator's Name: Operated Machine: Hours:

Yes 2,226

									Estimated Cost			
	E X C	GOOD	A V G	F A I R	P O O R	N / A	Comments	Parts	Labour	Tota		
General Appearance			X									
Instruments / Controls		X										
Cooling System Checks		X										
Engine Checks		X										
Transmission Checks						X						
Differential, Brakes and Final Drive Checks						x						
Hydraulic System Checks		X										
Chassis and Frame Checks			X									
Ground Engaging Tools			X									
Undercarriage			X				Undercarriage is original but new drive motors each side.					
Undercarriage Measurements												

ATTACHMENTS

	Item	Make	Туре	Size	Serial Number	Condition
Г	Bucket		Tilt	36"		Usable
	Clamp		Thumb			Usable

GROUND ENGAGING TOOLS

% remaining	NEW	GOOD	USABLE	R E P A I R	REPLACE	N / A	Comments	Parts	Labour	Total
50%			X							
50%			X							
									1	
								1	1	
40%			X							
	50% 50%	50% 50%	50% 50%	% remaining N W G O D A E E 50% X 50% X 50% X 1 X 1 1 1 1 1 1	% remaining N W O O O O O C H H H H H H H H H H H H H H	% remaining N W G O O A L E P A L E A C E 50% X X X 50% X X X 1 X X X 2 X X X 3 X X X 1 X X X	% remaining N G A C A A C A A C A A C A A C A A C A A C A A C A A C A A C A A C A C A C A C A C A C A C A C D C D D <thd< th=""> D <thd< th=""> D <thd< th=""> <thd< <="" td=""><td>% remaining N G A P A N Comments 50% I X I</td><td>% remaining N G V R R N A N A N A N Comments Parts Parts 50% V X V V V V V Parts Par</td><td>% remaining N G A PA LA N Comments Parts Labour 50% V <t< td=""></t<></td></thd<></thd<></thd<></thd<>	% remaining N G A P A N Comments 50% I X I	% remaining N G V R R N A N A N A N Comments Parts Parts 50% V X V V V V V Parts Par	% remaining N G A PA LA N Comments Parts Labour 50% V <t< td=""></t<>

UNDERCARRIAGE MEASUREMENTS

				E	Estimated Cost		
	Dimension	% remaining	Comments	Parts	Labour	Total	
Track Links		40%					
Track Bushings Chain sealed and lubricated? XYes O No Have pins/bushings been turned? O Yes XNo		30%					
Track Pitch		40%					
Grousers - Shoes		30%			1		
Idlers		40%			1 1		
Carrier Rollers		30%					
Track Rollers		40%				-	
Sprockets		30%					

ADDITIONAL PHOTOS





Model: 60D

Serial Number: FF060DX280238



Model: 60D

Serial Number: FF060DX280238



