DOGGETT

EVAL INSPECTION — QUICK — EXCAVATORS

2019 John Deere 350G LC stock: TT813360 serial: 1FF350GXAKF813360 Cab w/ AC • Short Arm • Standard Boom • 32" Pads • Coupler • 56" Bucket Warranty Unknown STORAGE LOCATION Doggett Heavy Machinery Services / 177166 Houston, TX, 77037 Contact:

PHOTOS (15 Total)



SUMMARY

| Overall Condition:GOODOverall Comments:Unit has active codes, Will need sorEvaluator's Name:Mario TrevinoOperated Machine:YesHours:4,382 | ne work. Over all in working condition. |
|--|---|
|--|---|

| | | | | | | | Estimated Cost | | | |
|--|-------------|------|-------------|------------------|------------------|-------------|--|-------|-------|-------|
| | E X C | GOOD | A V G | F A I R | P O O R | N / A | Comments | Parts | Labor | Total |
| General Appearance | | | X | | | | Rops damage (left side of door) | | | |
| Instruments / Controls | | | X | | | | | | | |
| Cooling System Checks | | | X | | | | A/C code:44 | | | |
| Engine Checks | | | X | | | | Codes; 2795-07 1569-31 641- 07 | | | |
| Transmission Checks | | | X | | | | | | | |
| Differential, Brakes and Final Drive Checks | | | X | | | | | | | |
| Hydraulic System Checks | | | X | | | | Low hydraulic oil level, potential leak. | | | |
| Chassis and Frame Checks | | X | | | | | | | | |
| Ground Engaging Tools | | X | | | | | | | | |
| Undercarriage | | | X | | | | | | | |
| Undercarriage Measurements | | | | | | | | | | |

ATTACHMENTS

| Ruckot Buckot 56" | Item | Make | Туре | Size | Serial Number | Condition |
|-------------------|--------|------|--------|------|---------------|-----------|
| | Bucket | | Bucket | 56" | | N/A |

GROUND ENGAGING TOOLS

| | | | | | | | | | Es | timated Co | ost |
|--------------|-------------|-----|------|----------------------------|----------------------------|---------|-------------|--|-------|------------|-------|
| | % remaining | NEW | GOOD | U S A B L E | R E P A I R | REPLACE | N / A | Comments | Parts | Labor | Total |
| Buckets | 60% | | X | | | | | | | | |
| Blades | | | | | | | X | | | | |
| Teeth / Tips | 50% | | | X | | | | | | | |
| End Bits | | | | | | | X | | | | |
| Cutting Edge | 50% | | | | x | | | Cutting edge on bucket teeth broken. | | | |

UNDERCARRIAGE MEASUREMENTS

| | | | | Es | ost | |
|---|-----------|-------------|----------|-------|-------|------|
| | Dimension | % remaining | Comments | Parts | Labor | Tota |
| Track Links | 123 | 90% | | | | |
| Track Bushings Chain sealed and lubricated? XYes ONo Have pins/bushings been turned? OYes XNo | 67 | 80% | | | | |
| Track Pitch | 867 | 90% | | | | |
| Grousers - Shoes | 30 | 90% | | | | |
| Idlers | 22.5 | 90% | | | | |
| Carrier Rollers | 148 | 90% | | | | |
| Track Rollers | 178 | 90% | | | | |
| Sprockets | N/A | 90% | | | | |

ADDITIONAL PHOTOS



Stock Number: TT813360

Model: 350G LC Serial Number: 1FF350GXAKF813360















Stock Number: TT813360

Model: 350G LC Serial Number: 1FF350GXAKF813360

